Products Improvement/Change Notice

Change Subject:	Tyre changer		Issue No.	PCT23003	Created on/by:	27.11.2023	Klaus Wu.	
Change reason:	Continuous improvement			Impleme ntation date :	20.11.2023	Issued on/by:	27.11.2023	Product service Dp.
Changed Item:	nanged Item: D186 Bead breaker cylinder			Class:	Important		Reply Deadline:	1
Universality for JFully Universal Partally Universa Non-Universal					Stable purchase of customers configured with D186 large			
Change Content:	Cancel the connector, install the exhaust valve directly on the cylinder			Issued to:	cylinder tyre changer Note: This change applies to the models listed below, corresponding to the models with suffixes.		Policy and Solution:	
Photos/Details: Old JZ06001060664 Exhaust valve is connected with the cylinder connector Connector NEW JZ06001020265 Exhaust valve is directly installed on the cylinder exhaust valve			Changed Machine Models:			This change is the continuous improvement design for our products . 1.We suggest all customers to accept this change, the advantages are as below: a. Connection between the exhaust valve and the cylinder is more stable; b. The synthetical properties of new design is better than old design. c. This change is free of charge. 2.We are doing the mass production with the new design. 3.If you agree to this change, we design now. If you are not sure whether agree to this change, we suggest you order one sample for testing right now. If you decide to produce your machine without this new design, please tell us the reason. 4.Please tell us your decision before reply deadline, Default consent without reply . Thank you!		